ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0524, W0925, W0923, W0522, W0526, W0536, W0937, W	NA	Poojamahalakshimi layout
Segment No.	**Total Length (m)**	
5/C-W0524/S054658	646.31	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	170.81	77.615621	13.098228	77.617187	13.098390	Poojamahalakshimi layout	1st cross road
2	104.64	77.616195	13.096755	77.616179	13.097701	Poojamahalakshimi layout	2nd cross road
3	110.41	77.616484	13.096755	77.616479	13.097753	Poojamahalakshimi layout	3rd cross road
4	209.87	77.616779	13.095882	77.616785	13.097779	Poojamahalakshimi layout	4th cross road
5	50.58	77.617117	13.097818	77.617125	13.097361	Poojamahalakshimi layout	5th cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road and drains at Poojamahalakshmi layout cross road in ward no. 05 in Thirumenahalli village limits	2500000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Asphalting	005-14-000047
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/596/2013-14	03/03/2014	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
04/03/2014	03/03/2015	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

B.R.Dhananjaya 0.00

Phone No. **E-Mail ID**

9591739363

Field Inspection Details

Number of Trees	Any Other Information	Name
0		chandrappa

Date of Inspection **Remarks**

22/02/2018

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0524, W0925, W0923, W0522,

esignation	Approver Name	Date	Target Date	Remark
E	Sri.R.L.Parameshwaraiah	23/02/2018	24/03/2018	As proposed
SE	Vasu K M	23/02/2018	24/03/2018	Completed
EE	mohandas	22/02/2018	24/03/2018	completed
AEE	sridhar	22/02/2018	24/03/2018	completed
AE	Chandrappa	22/02/2018	24/03/2018	Mobile verification is done
AE	Chandrappa	22/02/2018	24/03/2018	Forwarded



Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0524, W0925, W0923, W0522,